CORRES. CONTROL OUTGOING LTR NO.

DOE ORDER# _

93RF 14028

	_	
	LTR	ENC
AMARAL, M.E.		
BENEDETTI, R.L.	V	
BENJAMIN, A.		
BERMAN, H.S.	_	
BRANCH, D.B.		
CARNIVAL, G.J.	\neg	
COPP, R.D.		
DAVIS, J.G.		_
FERRERA, D.W.		\vdash
HANNI, B.J.		_
HARMAN, L.K.	—	\vdash
HEALY, T.J.		-
HEDAHL, T.		\vdash
HILBIG, J.G.		\vdash
LUTCHING NM	V	-
HUTCHINS, N.M.	_	
KIRBY, W.A.	_	<u> </u>
KUESTER, A.W.		<u> </u>
MAHAFFEY, J.W.		
MANN, H.P.	~	_
MARX, G.E.		L-
McDONALD, M.M.		_
McKENNA, F.G.		Ļ_
MONTROSE, J.K.		┖
MORGAN, R.V.		╙
POTTER, G.L.		
PIZZUTO, V.M. RISING, T.L.		
RISING, T.L.		
SANDLIN, N.B.		
SETLOCK, G.H.		
STEWART, D.L.		T
SULLIVAN, M.T.		Τ
SWANSON, E.R.		
WILKINSON, R.B.	$\overline{\mathbf{v}}$	1
WILLIAMS, S.(ORC)		Т
WILSON, J.M.	_	T
WYANT, R.D.		†
Primrase, AL		17
Laurin, PJ	Y	١ž
Busby, WS	V	17
13	Ď	17
	۲,	ᡟ
Burneister, M	1	łÝ
Vess MT	۲×	ĮΥ,
Wadel, RE CORRES. CONTROL	₩	₩
CORRES, CONTROL	台	łХ
ADMN RECORD/0802	۲	1 2
PATS/ THOS © 80	ĮΥ	12

CLASSIFICATION:

TRAFFIC

UCNI	
UNCLASSIFIED	
CONFIDENTIAL	
SECRET	

AUTHORIZED CLASSIFIER SIGNATURE

DOCUMENT CLASSIFICATION

DATELASSIFICATION OFFICE

IN REPLY TO REP CC NO

ACTION ITEM STATUS

PARTIAL/OPEN

CLOSED

LTR APPROVALS: ALP LOSS INITIALS
ORIG & TYPIST INITIALS
ALP LOSS

EG&G ROCKY FLATS

EG&G ROCKY FLATS, INC.

ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966-7000

November 12, 1993

93-RF-14028

James K. Hartman
Assistant Manager
Transition and Environmental Management
DOE, RFO

Attn: S. R. Grace, E. A. Dillé

SW-59 DIVERSION AND MODIFICATION TO THE SAMPLING PLAN FOR THE OPERABLE UNIT 2 SURFACE WATER INTERIM MEASURES/INTERIM REMEDIAL ACTION (11735) - NMH-587-93

In response to the above referenced request, the source of SW-59 is in the process of being characterized. To ensure that all water is collected, EG&G Rocky Flats, Inc. proposes to modify the seep areas as per the attached drawing. A trench will be excavated to a maximum depth of one foot across the downhill area of the new seep. The trench will be lined with bentonite and back filled with 1/2 inch diameter drain rock. This trench will be connected to the existing SW-59 collection sump and enable all contaminated water from this source to be collected and treated. No modifications to the Operable Unit 2 Interim Measures/Interim Remedial Action Sampling and Analysis Plan (SAP) will be required for this seep. However, the SAP is currently being modified to reflect current changes in sampling requirements.

Staff are currently available to perform the proposed work operating under Plant requirements. Modifications will be implemented after approval is received.

Millelin

N. M. Hutchins

Acting Associate General Manger Environmental Restoration Management

ALP:dql

Orig. and 1 cc - J. K. Hartman

CC

A. H. Pauole - DOE, RFO


R. J. Schassburger -


M. N. Silverman

ADMIN RECUE

BZ -A-00079

RF-46469 (Rev. 9/93)





OPERABLE UNIT 2 SURFACE WATER COLLECTION ____ new ____ existing

LEGEND